This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

Yoshiko HOSHIYAMA et al. Q79583 METHOD FOR EJECTING LIQUID, LIQUID EJECTING APPARATUS, Filing date: January 27, 2004 Darryl Mexic 202-663-7909 1 0f 18






FIG. 1




sensor


Yoshiko HOSHIYAMA et al. Q79583 METHOD FOR EJECTING LIQUID, LIQUID EJECTING APPARATUS, Filing date: January 27, 2004 Darryl Mexic 202-663-7909 3 of 18




Yoshiko HOSHIYAMA et al. Q79583 METHOD FOR EJECTING LIQUID, LIQUID EJECTING APPARATUS, Filing date: January 27, 2004 Darryl Mexic 202-663-7909 4 of 18



Yoshiko HOSHIYAMA et al. Q79583 METHOD FOR EJECTING LIQUID, LIQUID EJECTING APPARATUS, Filing date: January 27, 2004 Darryl Mexic 202-663-7909 5 of 18



Yoshiko HOSHIYAMA et al. Q79583 METHOD FOR EJECTING LIQUID, LIQUID EJECTING APPARATUS, Filing date: January 27, 2004 Darryl Mexic 202-663-7909 6 of 18



Yoshiko HOSHIYAMA et al. Q79583 METHOD FOR EJECTING LIQUID, LIQUID EJECTING APPARATUS, Filing date: January 27, 2004 Darryl Mexic 202-663-7909 7 of 18




FIG. 7

EJECTING APPARATUS,Filing date: January 27, 2004
Darryl Mexic 202-663-7909
8 of 18




FIG. 8

9/18





FIG. 9






FIG. 11

Yoshiko HOSHIYAMA et al. Q79583 METHOD FOR EJECTING LIQUID, LIQUID EJECTING APPARATUS, Filing date: January 27, 2004 Darryl Mexic 202-663-7909 12 of 18

Please look at the printed sheet, select the number of the pattern with the least roughness from the list for #1 - #3 by clicking the V below, and click the "next" button.

If there is no appropriate pattern and all of the patterns seem rough, then select the number of the pattern with the least roughness and click the "readjustment" button.

A sheet for Bi-d adjustment will be re-printed.

Further, if there are modes that do not require readjustment among #1 - #3, then turn the check on the right of the list OFF for those modes.

92 #1 1 V 95

93 #2 4 V 96

Only click the "readjustment"/"next >" button after you have confirmed the printed sheet and made settings.

FIG. 12




FIG. 13




FIG. 14

Yoshiko HOSHIYAMA et al. Q79583 METHOD FOR EJECTING LIQUID, LIQUID EJECTING APPARATUS, Filing date: January 27, 2004 Darryl Mexic 202-663-7909 15 of 18




FIG. 15




FIG. 16

Yoshiko HOSHIYAMA et al. Q79583 METHOD FOR EJECTING LIQUID, LIQUID EJECTING APPARATUS, Filing date: January 27, 2004 Darryl Mexic 202-663-7909 17 of 18

